

User Schedule 2006/II

Aug. 2006		Sept. 2006		Oct. 2006		Nov. 2006		Dec. 2006		Jan. 2007		Feb. 2007	
1	31	1		1	16b	1	Buffer	1		1		1	
2		2	Uniform	2	40	2	2	2	Uniform	2	1	2	
3		3		3	M D T	3	*	3		3		3	16b
4		4	36	4		4	1/3	4	49	4		4	
5		5	M D T	5		5		5	M D T	5		5	6
6		6		6	16b	6	45	6		6		6	M D T
7	32	7		7		7	M D T	7	2	7		7	M D T
8		8	Uniform	8		8		8	*	8	2	8	
9		9		9	41	9		9	1/3	9		9	
10		10		10	M D T	10	Uniform	10		10		10	16b
11		11	37	11		11		11	50	11		11	
12		12	M D T	12	4	12		12	M D T	12		12	7 Rad
13		13	PSS	13	*	13	46	13		13		13	M D T
14	33	14		14	10 mA	14	M D T	14		14		14	
15		15	H	15		15		15	Uniform	15	3	15	
16		16		16	42	16	2	16		16		16	
17		17		17		17	*	17		17		17	Uniform
18	Restart	18	38	18		18	1/3	18	51	18		18	
19	M D T	19	M D T	19		19		19		19	Restart	19	8
20	M D T	20		20		20	47 Rad	20		20	M D T	20	M D T
21	M D T	21		21		21	M D T	21		21	M D T	21	
22	34	22	16b	22		22		22		22	M D T	22	
23	Buffer	23		23	43	23		23		23	4	23	2
24	Uniform	24		24		24	Uniform	24	52	24	Buffer	24	*
25		25	39	25		25		25		25	16b	25	1/3
26	Uniform	26	M D T	26		26		26		26		26	9
27		27		27	Restart	27	48	27		27	16b	27	
28	35	28		28	M D T	28	M D T	28		28		28	M D T
29	M D T	29	16b	29	M D T	29		29		29	5	29	
30		30		30	M D T	30	Uniform	30		30	M D T	30	
31	Uniform			31	44 Buffer	31		31		31	16b	31	

End 2006/II:

2006/II: 22 August 2006 to 28 February 2007

1 March 2007,
08:00

M D T	Shut-down	2*1/3	2 * 1/3 filling	Unif	Uniform filling
PSS	MDT	H	Hybrid mode	16b	16 bunch
Rad	PSS tests	Rad	Radiation Tests	4*10mA	4 * 10 mA

Note: 2*1/3 fill replaces Uniform filling

31 October to 7 November 2006

15 to 21 November 2006

6 to 12 December 2006

21 to 28 February 2007